

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14 Pad

Location ID: 335234



Photo # 423 From entrance to location



Photo # 424 Location

**Inspection Photos**  
**Location Name: MUSTANG RESOURCES LLC Mead 24-14 Pad**  
**Location ID: 335234**



**Photo # 425 Location**



**Photo # 426 Location**



**Inspection Photos**  
**Location Name: MUSTANG RESOURCES LLC Mead 24-14 Pad**  
**Location ID: 335234**



**Photo # 427 Location**



**Photo # 428 Location**



## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14 Pad

Location ID: 335234



Photo # 442 Tank not properly labeled/missing required information



Photo # 443 Tank not properly labeled/missing required information



## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14 Pad

Location ID: 335234



Photo # 444 Open ended load line



Photo # 445 Open ended load line



## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14 Pad

Location ID: 335234



**Photo # 446 Stained soils & gravel inside tank battery secondary containment**



**Photo # 468 Stained soils & gravel inside tank battery secondary containment/fluid running down side of tank**



## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14 Pad

Location ID: 335234



**Photo # 450 Secondary containment not sufficient to contain spilled or released materials**



**Photo # 451 Secondary containment not sufficient to contain spilled or released materials**



## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14 Pad

Location ID: 335234



**Photo # 452 Secondary containment not sufficient to contain spilled or released materials**



**Photo # 453 Secondary containment not sufficient to contain spilled or released materials**



## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14 Pad

Location ID: 335234



Sep 22, 2023 at 12:27:46 PM  
CO

Photo # 463 Fluid leaking from swedge on tank



Sep 22, 2023 at 12:28:32 PM  
CO

Photo # 469 Stained soils & gravel inside tank battery  
secondary containment/fluid running down side of tank

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14 Pad

Location ID: 335234



Photo # 470 Swedge leaking & fluid running down tank



Photo # 471 Stained soils & gravel inside tank battery secondary containment/fluid running down tank



## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14 Pad

Location ID: 335234



**Photo # 489 Hole in production tank flowline & fluid leaking out**




**Photo # 494 Hole in production tank flowline & fluid leaking out**

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC Mead 24-14 Pad

Location ID: 335234



**Photo # 498 Supply gas disconnected from A valve & stainless fitting propping valve open**



**Photo # 499 Supply gas disconnected from A valve & stainless fitting propping valve open**