

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 13-23 Pad

Location ID: 335508



Photo # 206 From entrance to location



Photo # 207 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 13-23 Pad

Location ID: 335508



Photo # 208 Location



Photo # 209 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 13-23 Pad

Location ID: 335508



Photo # 210 Location



Photo # 215 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 13-23 Pad

Location ID: 335508



Sep 22, 2023 at 10:48:53 AM
CO

Photo # 222 Location



Sep 22, 2023 at 10:49:18 AM
CO

Photo # 223 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 13-23 Pad

Location ID: 335508



Photo # 230 RWF 313-23 & 413-23 wellhead signs weathered & illegible.



Photo # 221 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 13-23 Pad

Location ID: 335508



Photo # 226 Debris



Photo # 247 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RWF 13-23 Pad

Location ID: 335508



Photo # 248 Debris