

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2023

Submitted Date:

09/19/2023

Document Number:

699107380

FIELD INSPECTION FORMLoc ID 317706 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10528

Name of Operator: ARCH OIL & GAS LLC

Address: 16400 DALLAS PARKWAY SUITE 305

City: DALLAS State: TX Zip: 75248

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HEASLIP, TRACY	(239) 404-0929	theaslip@archog.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
317706	LOCATION	AC			-	ELMER KAUFMAN-62N63W 18SWSE	SI

General Comment:

This is a follow up to prior inspection document #699106873. Overgrown vegetation has been removed. NFPA placard and capacity label have not been done. Operator sign is not current at the tank battery.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Pit is missing capacity label. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h		Date: 10/27/2023
Type	BATTERY		
Comment:	Incorrect operator sign needs to be updated. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.g.		Date: 10/27/2023
Type	TANK LABELS/PLACARDS		
Comment:	NFPA placard appears to be weathered and needs to be replaced. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h		Date: 10/27/2023

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 317706 Type: LOCATION API Number: - Status: AC Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI Tank Battery

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Tuesday 9/19/23 at approximately 0946hrs I, Inspector Adam Burns, Conducted an on-site inspection at Elmer Kaufman-62N63W 18SWSE Tank Battery of KP Arch Oil & Gas LLC.</p> <p>Location ID #317706 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Incorrect operator sign needs to be updated. Install sign to comply with Rule 605.g. With a Corrective Action date of 10/27/23</p> <p>Pit is missing capacity label. Install sign to comply with Rule 605.h. With a Corrective Action date of 10/27/23</p> <p>NFPA placard appears to be weathered and needs to be replaced. Install sign to comply with Rule 605.h. With a Corrective Action date of 10/27/23</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	burnsa	09/19/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
403534853	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6255821
699107381	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6255796