

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2023

Submitted Date:

09/19/2023

Document Number:

702501872

FIELD INSPECTION FORMLoc ID 313060 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10776

Name of Operator: CROWHEART ENERGY LLC

Address: 1225 17TH STREET SUITE 2950

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|--------------------------------|---------|
| Fiddles, Callie | (720) 738-9443 | c.fiddles@crowheartenergy.com | |
| , Regulatory | | regulatory@crowheartenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 223491 | WELL | TA | 09/01/2020 | GW | 081-06857 | PEPLER FEE COM 12-18 | TA |

General Comment:**ECMC Inspection Report Summary**

On Tuesday, 09/19/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Crowheart Energy LLC on the Pepler Fee Com 12-18 well, Location #313060, in Moffat County, Colorado.

This location is within or in close proximity to a CPW District with High Priority, NSO, and Density Habitat Regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Inspection #702501380 on 5/24/23. All Corrective Actions have not been resolved and original due dates will remain,

1. Random debris. (Incomplete)
2. Unused equipment. (Removed)
3. Burner stack on separator and lines open to wildlife. (Removed)
4. Unlabeled fiberglass tanks on location. (Removed)
5. Wellhead sign missing required information. (Emergency number written in)
6. Unmarked anchors (Unmarked anchor)

Refer to Inspection Photos for observed compliance issues.

While on location the following compliance issues were observed,

1. Unmarked anchor.
2. Debris.
3. Wellhead sign illegible.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|--|-------|------------|
| Type | WELLHEAD | | |
| Comment: | Wellhead sign illegible | | |
| Corrective Action: | Operators will ensure that signs are well maintained and legible | Date: | 10/20/2023 |

Emergency Contact Number:

| | | | |
|--------------------|--------------|-------|--|
| Comment: | 800-967-2801 | | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | DEBRIS | | |
| Comment: | Random debris | | |
| Corrective Action: | Remove debris around wellhead and removed production equipment area | Date: | 06/01/2023 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|--------------------------|---|-------|-----------------|
| Type: Deadman # & Marked | # 3 | | corrective date |
| Comment: | 4th anchor unmarked. Marker on the ground | | |
| Corrective Action: | Securely mark all anchors | Date: | 06/09/2023 |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | | | | | | |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 223491 | Type: | WELL | API Number: | 081-06857 | Status: | TA | Insp. Status: | TA |
| Idle Well | | | | | | | | | |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned | | | | | | | | | |
| Reminder: | | | | | | | | | |
| Comment: MIT - 7/21/2020. | | | | | | | | | |
| Corrective Action: | | | | | | | | | |
| Date: | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403535373 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6256466 |
| 702501874 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6256460 |