

WELL NAME: HILL RANCH 04-15V, API #: 071-07148, INSP. # 695108698




PHOTO 1: WELL SIGN





**PHOTO 2: LOCATION**







**PHOTO 3: V WELLHEAD AND EQUIPMENT**







**PHOTO 4: WELLHEAD/ AREA OF IMPACTED SOIL NEAR R WELLHEAD APPEARS TO BE FROM LEAKING HYDRO HOSES IN THE PAST, HOSED DID NOT APPEAR TO BE LEAKING AT TIME OF INSPECTION. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D (BE SURE TO INSPECT HYDRO HOSES AND CONNECTIONS FOR ANY LEAKS AND REPAIR. CA DATE 10-26-2023.**

