

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad

Location ID: 323788



Photo # 858 From entrance to location



Photo # 859 Location

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad

Location ID: 323788



Photo # 860 Location



Photo # 861 Meter calibration info not conspicuously posted. Door to meter house has a lock on it, unable to check/verify cal card.

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad

Location ID: 323788



Photo # 862 Meter calibration info not conspicuously posted. Door to meter house has a lock on it, unable to check/verify cal card.



Photo # 863 Weeds/undesirable plant species

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad

Location ID: 323788



Photo # 864 Weeds/undesirable plant species



Photo # 865 Weeds/undesirable plant species

Inspection Photos

Location Name: MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad

Location ID: 323788



Photo # 866 Weeds/undesirable plant species