

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2023

Submitted Date:

09/26/2023

Document Number:

708901795

FIELD INSPECTION FORMLoc ID 323788 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10550

Name of Operator: MUSTANG RESOURCES LLC

Address: 1660 LINCOLN STREET SUITE 1450

City: DENVER State: CO Zip: 80264

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210809	WELL	PR	12/01/2016	GW	045-06567	MOORE 27-42-6S-94W	PR

General Comment:**CECMC Inspection Report Summary**

On 09/25/2023 at approximately 13:16 hours, I, Compliance Specialist, Wayne Smelser
Conducted an on-site inspection at MUSTANG RESOURCES LLC MOORE 27-42-6S-94W Pad.

Location # 323788 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Nest/Roost sites & in close proximity to NSO Habitat area.

Location is approximately 104 yards from the Colorado River & 321 yards from Porcupine Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Weeds/Undesirable Plant Species on location with a CA date of 10/03/2023
2. Equipment - Meter calibration info not conspicuously posted with a CA date of 10/06/2023
4. Stormwater - Erosion & transport of sediment on location with a CA date of 10/11/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	No tank battery			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/888-291-8588			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds/Undesirable Plant Species on location			
Corrective Action:	Oil & gas locations will be kept free of undesirable plant species.			Date: 10/03/2023
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Gas Meter Run	# 1			corrective date
Comment:	Meter calibration info not conspicuously posted. Door to meter house has a lock on it, unable to check/verify cal card.			
Corrective Action:	The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.			Date: 10/06/2023
Type: Bradenhead	# 1			
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.			
Corrective Action:				Date:
Type: Plunger Lift	# 0			
Comment:	Well is not on plunger lift			
Corrective Action:				Date:
Type: Deadman # & Marked	# 1			
Comment:	Marked			

Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	210809	Type:	WELL	API Number:	045-06567	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well not on plunger lift								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Fail					Erosion & transport of sediment on location
		Gravel				Sparse in some areas
Compaction						
Gravel						Sparse to none
		Compaction				

Comment: 1. Erosion & transport of sediment on location

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 10/11/2023

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Please refer to Housekeeping, Equipment & Stormwater for observed compliance issues.	smelserw	09/26/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708901796	Inspection 708901795 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6265028
708901797	Inspection 708901795 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6265029