

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/26/2023

Submitted Date:

09/26/2023

Document Number:

713300124

FIELD INSPECTION FORM

 Loc ID 318728 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|--------------------------|---------------------------------|
| , KPK | | cogcc@kpk.com | All Inspections |
| Silver, Randy | | randy.silver@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 242038 | WELL | PR | 02/01/2023 | OW | 123-09829 | JACOBUCCI 4 | PR |

General Comment:

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|--|
| | Type WELLHEAD | | |
| | Comment: good | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:
 Corrective Action: Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|---|-------|--|
| | Type WELLHEAD | | |
| | Comment: wirw | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | | | corrective date |
|---|--|-----|--|-------|-----------------|
| Type: Pump Jack | | # 1 | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Prime Mover | | # 1 | | | |
| Comment: electrical motor | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Bradenhead | | # 1 | | | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Type: Ancillary equipment | | # 1 | | | |
| Comment: electrical panel | | | | | |
| Corrective Action: | | | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|----------|--|--|--|
| Type | | | |
| Comment: | | | |

Corrective Action:

Date:

Inspected Facilities

Facility ID: 242038 Type: WELL API Number: 123-09829 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/15/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|------------------------------------|---------|------------|
| Routine inspection | kesterm | 09/26/2023 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 713300125 | site pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6265262 |