

Inspection Photos
Maralex Gosney 1
API 067-06570



Photo #1. View of corrective action identified in FIR Doc.#712700541.



Photo #2. View of corrective action not completed. Weeds growing around separator, wellhead, and across location.

Inspection Photos
Maralex Gosney 1
API 067-06570



Photo #3. View of corrective action identified in FIR Doc.#712700541.



Photo #4. View of corrective action not completed. Weeds growing around wellhead, separator, and across location.

Inspection Photos
Maralex Gosney 1
API 067-06570



**Photo #5. View of corrective action identified in FIR
Doc.#712700541.**

**Photo #6. View of corrective action not completed. Weeds
growing around wellhead, separator, and across location.**