

Inspection Photos Maralex Gosney 1-A API 067-09255



Photo #1. View of corrective action identified in FIR Doc.#712700542.



Photo #2. View of corrective action not completed at the #1-A wellhead, disconnected containers.

Inspection Photos Maralex Gosney 1-A API 067-09255



Photo #3. View of non-legible container labeling at the #1-A wellhead.




Photo #4. View of non-legible container labeling at the #1-A wellhead.

Inspection Photos
Maralex Gosney 1-A
API 067-09255



**Photo #5. View of corrective action identified in FIR
Doc.#712700542.**



**Photo #6. View of corrective action not completed. No tank
volume posted.**

Inspection Photos
Maralex Gosney 1-A
API 067-09255



Photo #7. View of corrective action identified in FIR Doc.#712700542.



Photo #8. View of corrective action not completed. Sections of fencing on ground.

Inspection Photos
Maralex Gosney 1-A
API 067-09255



**Photo #9. View of corrective action identified in FIR
Doc.#712700542.**



**Photo #10. View of corrective action not completed.
Impacted material on ground at the #2-A wellhead.**

**Inspection Photos
Maralex Gosney 1-A
API 067-09255**



**Photo #11. View of corrective action identified in FIR
Doc.#712700542.**



**Photo #12. View of corrective action not completed. Weeds
growing within tank battery berm.**