

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate beginning to fade and will need replaced in the near future		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>	Date:	<input style="width: 100%;" type="text"/>

Good Housekeeping:

Type	WEEDS		
Comment:	undesirable vegetation growing tall in and around the location		
Corrective Action:	Comply with rule 606	Date:	10/06/2023

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	ancillary equipment has fabricated steel pipe and round stock		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment	# 1		
Comment:	electric panel, meter box and transformers		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appearsto be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:		Date:	

Flaring:

Type	<input style="width: 100%;" type="text"/>		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241226 Type: WELL API Number: 123-09014 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/11/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Thursday 9-28-2023 at approximately 1415 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: This is a Routine Field Inspection any CA from previous inspections are still active, valid and needs addressed. Operator: KP Kauffman Location name: 1415 Corp Unit F1 API #05-123-09014 County: Weld Weather: Clear, Sunny. Location: Dry. While there, I observed a wellsite, SI at the time of the inspection. During this inspection, I observed the following possible compliance issues: 606 housekeeping: CA date 10-6-2023. See attached photos and video. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	09/28/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702402408	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6267831