

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/23/2023

Submitted Date:

09/28/2023

Document Number:

698601023

**FIELD INSPECTION FORM**Loc ID 316889 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 710

Name of Operator: AEON ENERGY CORP

Address: 2600 SOUTH LEWIS WAY #102

City: LAKEWOOD State: CO Zip: 80227

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

6 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Snyder, Barry	303-922-0590	aeonco@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280793	WELL	IJ	02/01/2023	DSPW	115-06062	HV RANCH 32-1	IJ

**General Comment:**

Routine Inspection.

The name change of the Colorado Oil and Gas Conservation Commission to the Energy & Carbon Management Commission required major server updates and created sync issues for remote field personnel's computers. During this time personnel were not able to complete and uploaded inspections creating a lengthy lag between inspection dates and report submission dates. These circumstances are beyond the Operators control and required dates should be adjusted to match Inspectors FIR submission date. All corrective action dates have been adjusted to accommodate actual FIR submission date. Please contact me directly with any questions or concerns.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Two track off maintained county road. Two track into location has not been maintained.			
Corrective Action	Repair and maintain lease road to comply with rule 603.l.			Date: 10/29/2023
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	BATTERY			
Comment:	Battery sign posted on tank staircase. Sign not posted or information inaccurate at battery.			
Corrective Action:	Install sign to comply with Rule 605.e.			Date: 11/29/2023
Type	WELLHEAD			
Comment:	Sign not posted at well.			
Corrective Action:	Install sign to comply with Rule 605.d.			Date: 10/29/2023
Type	TANK LABELS/PLACARDS			
Comment:	Tanks have no contents/quanity/Hazard signage.			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 11/29/2023
Emergency Contact Number:				
Comment:	Emergency contact information posted on Tank Battery sign.			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	WEEDS			
Comment:	Well site and Tank Battery is over grown with vegetation and weeds.			
Corrective Action:	Comply with Rule 606.			Date: 10/06/2023
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	LOCATION			
Comment:	Post and wire fencing.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Other	# 1			corrective date
Comment:	Metal Equipment Shed inside tank battery berms.			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Wellhead. Tubing in wellbore. Tubing valve open. Casing valve closed, not connected. Bradenhead valve closed.			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	2	OTHER	FIBERGLASS AST		,
Comment:	Tanks do not have contents/quantity/hazard signs or placards.				
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)	Not identified.	
Other (Capacity)	Not marked.	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Base and walls of bermed secondary containment is over grown with vegetation and not sufficiently impervious to contain spilled or released materials due to root penetration.			
Corrective Action:	Repair walls and base or install liner material to ensure spill or released materials will be maintained with containment structure.			Date: 10/29/2023

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	280793	Type:	WELL	API Number:	115-06062	Status:	IJ	Insp. Status:	IJ

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
The name change of the Colorado Oil and Gas Conservation Commission to the Energy & Carbon Management Commission required major server updates and created sync issues for remote field personnel's computers. During this time personnel were not able to complete and uploaded inspections creating a lengthy lag between inspection dates and report submission dates. These circumstances are beyond the Operators control and required dates should be adjusted to match Inspectors FIR submission date. All corrective action dates have been adjusted to accommodate actual FIR submission date. Please contact me directly with any questions or concerns.	stjohnw	09/28/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698601089	Inspection Photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6267993">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6267993</a>