

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/21/2023

Submitted Date:

09/28/2023

Document Number:

710500042

FIELD INSPECTION FORM

Loc ID 480547 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 17180
Name of Operator: CITATION OIL & GAS CORP
Address: 14077 CUTTEN RD
City: HOUSTON State: TX Zip: 77069

Findings:

- 10 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Sanchez, Chris		chris.sanchez@state.co.us	
Welsh, Brian		brian.welsh@state.co.us	
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	COGC
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	COGC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480624	TANK BATTERY	AC	08/30/2021		-	Gray's-State Battery	EI

General Comment:

This is an Environmental Inspection for the Gray's-State Battery Well Location, Facility # 480624 Located In Cheyenne County, CO

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3		STEEL AST		
Comment: No issues observed at the time of inspection					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Berms were earthen with no liner. Containment floor was earthen with no liner				
Corrective Action:				Date:

Wells Served By Facilities Above

AirsID

API Number

017-06692

017-06672

API Number

AirsID

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	Date: _____

Inspected Facilities

Facility ID: 480624 Type: TANK API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: OIL Estimated Spill Volume: 90

Comment: There is an open spill associated with this location, Spill ID # 403499590, at this time, estimates by the operator indicated 90 BBL of oil and an unknown amount of produced water spilled at the location. Operator identified approximately 700 BBL of produced water was recovered.

Corrective Action: Operator shall continue cleanup efforts of stained soil and continue working to remediate the affected areas per Rule 912 Date: 11/14/2023

Reportable: YES GPS: Lat 38.959325 Long -103.055744

Proximity to Surface Water: _____ Depth to Ground Water: 75

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Piles	Adequate		
Comment		A stockpile of oily soil observed on Location within a Lined Earthen Berm		
Corrective Action		Operator shall dispose of impacted soil in compliance of Rules 902.c. 902.f. or 905...		Date: <u>11/14/2023</u>

Spill/Remediation:

Comment: During the time of inspection, impacted soil observed throughout the Tank Battery Containment.

Corrective Action: Operator shall continue cleanup efforts of stained soil and continue working to remediate the affected areas per Rule 912. If remediation of the affected areas exceeds 90 days of initial spill date, the Operator shall submit an Initial Form 27 to continue cleanup efforts Date: 11/14/2023

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
There was a partially buried Vessel on location missing netting or a cover to prevent animals from entering the vessel. Comply with Rule 608.a.(13)	sanchezcc	09/28/2023
Operator shall continue spill cleanup efforts per Rule 912.	sanchezcc	09/28/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500043	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6268003