

Operator: 8 North

Location Name: DF RANCH-611N61W 2SWSW

Loc ID: 461586

Inspection: 696305276



Exhibit A



Exhibit B

CA: North Tank Capacity labels faded and are no longer visible. Install signs to comply with rule 605.h.

CA Resolution: Capacity labels have been installed to the north tank to comply with Rule 605.h.



Exhibit A

CA: Unused barbed wire on northeast side of location. Comply with rule 606.

CA Resolution: Unused barbed wire has been removed and properly disposed of to comply with Rule 606.



Exhibit A




Exhibit B



Exhibit C

CA: Stained soils at west tanks. For localized stained soils or oily waste- “properly dispose of oily waste in accordance with 905.e.”

CA Resolution: Stained soils near west tanks has been addressed by Operator and properly disposed of to comply with Rule 905.e.