

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403544183

Date Received:

09/28/2023

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name  
Labowskie, Steve  
\_General

Phone

Email

steve.labowskie@state.co.us

FarmingtonRegulatoryTechs@hilcorp.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 712700659

Inspection Date: 09/14/2023

FIR Submit Date: 09/15/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

### LOCATION - Location ID: 325510

Location Name: DAVIS GAS UNIT-N33N10W Number: 4NENW County: LA PLATA

Qtrqr: NENW Sec: 4 Twp: 33N Range: 10W Meridian: N

Latitude: 37.137310 Longitude: -107.942500

### FACILITY - API Number: 05-067- -00 Facility ID: 214920

Facility Name: DAVIS GAS UNIT Number: 1

Qtrqr: NENW Sec: 4 Twp: 33N Range: 10W Meridian: N

Latitude: 37.137310 Longitude: -107.942500

### CORRECTIVE ACTIONS:

1 ☒ CA# 181213

Corrective Action: Mark per Rule 1003.a. or remove not serviceable or no longer needed for ongoing operations.

Date: 09/29/2023

Response: CA COMPLETED

Date of Completion: 09/27/2023

Operator Comment: Marked all rig anchors on location. See attached photos.

COGCC Decision:

Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 181214

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 09/29/2023

Response: CA COMPLETED

Date of Completion: 09/27/2023

Operator  
Comment:

Installed and repaired BMPs on eastern side of location and mitigated sediment migration off location. Repaired and reinforced overwhelmed ditch and Berm along west side of location. See attached photos

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech

Date: 9/28/2023 10:10:57 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403544183	FIR RESOLUTION SUBMITTED
403544185	Davis Gas Unit 1_712700659_Resolved Photos

Total Attach: 2 Files