

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2023

Submitted Date:

09/15/2023

Document Number:

695108643

FIELD INSPECTION FORMLoc ID 333348 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	All Inspections
Costa, Ryan		ryan.costa@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436941	WELL	PR	12/28/2015	CO2	055-06314	SHEEP MOUNTIAN UNIT 4-23 L	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:	PHOTO 4: There is no labeling at the chemical tank next to the well.		
Corrective Action:	Install sign to comply with Rule 605.h. THIS IS THE SECOND NOTICE OF THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED.	Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 5: There is a dripping leak coming from the chemical tank line next to the well and there is no lid on the tank.		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION IS REQUIRED.	Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	WELLHEAD AND SIGN IS OFF TO THE SIDE OF LOCATION DUE TO THE WORKOVER THAT OPERATOR JUST COMPLETED. THIS EQUIPMENT MUST BE PUT BACK IN USE ASAP.		
Corrective Action:		Date:	

Equipment:

Type: Other	# 1		corrective date
Comment:	CHEM TANK IS OFF TO THE SIDE OF LOCATION. CORRECTIVE ACTION NOTED ABOVE MUST BE COMPLETE AND EQUIPMENT PUT BACK IN USE OR THIS EQUIPMENT MUST BE REMOVED FROM LOCATION.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 436941 Type: WELL API Number: 055-06314 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 10/04/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 280 Fluid Type: WATER AND LIQUID HYDROCARBONEnd Surf Csg Pressure: 150Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403539542	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6262404
695108644	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6262397