

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/28/2023

Submitted Date:

09/28/2023

Document Number:

699505037

FIELD INSPECTION FORM

Loc ID 443722	Inspector Name: MEDINA, JUSTIN	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 2 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10633 Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC Address: 1801 CALIFORNIA STREET #2500 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443723	WELL	PR	11/01/2018	OW	005-07249	Prosper Farms 4-65 2-1 4AH	PR
443724	WELL	PR	11/08/2017	OW	005-07250	Prosper Farms 4-65 2-1 4CH	PR
483657	WELL	DG	01/22/2023		005-07513	Property Reserve 4-65 3-4 4AH	DG
483658	WELL	DG	01/26/2023		005-07514	Prosper Farms 4-65 2-1-6 2BH	DG
483659	WELL	DG	01/24/2023		005-07515	Prosper Farms 4-65 2-1-6 1BH	DG
483660	WELL	DG	01/27/2023		005-07516	Prosper Farms 4-65 2-1-6 3AH	DG
483661	WELL	DG	01/25/2023		005-07517	Prosper Farms 4-65 2-1-6 2AH	DG
483662	WELL	DG	01/29/2023		005-07518	Prosper Farms 4-65 2-1-6 3CH	DG
483663	WELL	DG	01/28/2023		005-07519	Prosper Farms 4-65 2-1-6 3BH	DG
483664	WELL	DG	01/23/2023		005-07520	Prosper Farms 4-65 2-1-6 1AH	DG
483665	WELL	DG	01/20/2023		005-07521	Property Reserve 4-65 3-4 3BH	DG
483666	WELL	DG	01/18/2023		005-07522	Property Reserve 4-65 3-4 1AH	DG
483667	WELL	DG	01/19/2023		005-07523	Property Reserve 4-65 3-4 1BH	DG

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 443723 Type: WELL API Number: 005-07249 Status: PR Insp. Status: PR

Facility ID: 443724 Type: WELL API Number: 005-07250 Status: PR Insp. Status: PR

Facility ID: 483657 Type: WELL API Number: 005-07513 Status: DG Insp. Status: DG

Well StimulationStimulation Company: HaliburtonStimulation Type: HYDRAULIC FRAC**Observation:**

Other: _____

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: Fluid: _____ Gas: _____

Comment: At time of inspection pump pressure was 8200 PSIG. Ball was dropped to perform frac on next stage. Walk around inspection with company representative, and did visual inspection of location.

Corrective Action: _____

Date: _____

Facility ID: 483658 Type: WELL API Number: 005-07514 Status: DG Insp. Status: DG

Facility ID: 483659 Type: WELL API Number: 005-07515 Status: DG Insp. Status: DG

Facility ID: 483660 Type: WELL API Number: 005-07516 Status: DG Insp. Status: DG

Facility ID: 483661 Type: WELL API Number: 005-07517 Status: DG Insp. Status: DG

Facility ID: 483662 Type: WELL API Number: 005-07518 Status: DG Insp. Status: DG

Facility ID: 483663 Type: WELL API Number: 005-07519 Status: DG Insp. Status: DG

Facility ID: 483664 Type: WELL API Number: 005-07520 Status: DG Insp. Status: DG

Facility ID: 483665 Type: WELL API Number: 005-07521 Status: DG Insp. Status: DG

Facility ID: 483666 Type: WELL API Number: 005-07522 Status: DG Insp. Status: DG

Facility ID: 483667 Type: WELL API Number: 005-07523 Status: DG Insp. Status: DG

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were warm, calm, clear.	medinaj	09/28/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699505038	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6270580