

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/02/2023

Submitted Date:

10/02/2023

Document Number:

702501921

FIELD INSPECTION FORMLoc ID 314686 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 12930

Name of Operator: CALCO DBA CALLISTER CO

Address: 1230 W 1400 N

City: LEHI State: UT Zip: 84043

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Callister, Jan	(801) 487-4721	jec-apex@outlook.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229262	WELL	TA	06/01/2021	GW	103-06357	CALLISTER- GOVERNMENT 3	TA

General Comment:**ECMC Inspection Report Summary**

On Monday, 10/02/2023, Inspector Kirby Burchett, conducted a follow up field inspection at CALCO dba Callister Co. on the Callister-Government 3 well, Location #314686, in Rio Blanco County, Colorado.

This location is within or in close proximity to a CPW District with High Priority, NSO, and Density Habitat Regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Inspection #702501675 on 7/12/23. Well has since been plugged. Waiting to cut off wellhead and verify cement tops.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: 801-571-5890 / 970-620-2257 or 911

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Other

1

Comment: Wellhead

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	229262	Type:	WELL	API Number:	103-06357	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Well has been plugged. 5 day minimum waiting period before cutting off wellhead									
Corrective Action: Submit 42 - Notice of Operations 48 hours before cutting off wellhead. Compliance Inspector may verify cement tops before installing marker.									
Date: 10/03/2023									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT