

Thacker 1

Document number 712700685

Date completed 10/2/2023

Cleaned up contaminated soil around wellhead and pump jack skid

