

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/02/2023

Submitted Date:

10/03/2023

Document Number:

702501923

FIELD INSPECTION FORMLoc ID 314354 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10605

Name of Operator: APEX OIL VENTURES INC

Address: 8823 S. REDWOOD ROAD #D-1

City: WEST JORDAN State: UT Zip: 84088

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Callister, Jan E	(808) 571-5890	jec-apex@outlook.com	
Engineering, ECMC		dnr_cogccengineering@state.co.us	
Rasmussen, Terry	(801) 487-4721	t.rasmussen@outlook.com	
Callister, Andrew	(801) 455-8366	andy@qualityoilproperties.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228525	WELL	SI	06/01/2023	GW	103-05400	P.R.-TRIGOOD-GOV'T (0365) 10	TA

General Comment:**ECMC Inspection Report Summary**

On Monday, 10/02/2023, Inspector Kirby Burchett, conducted a routine field inspection at APEX Oil Ventures Inc on the P.R.-Trigood-Gov't (0365) 10 well, Location #314354, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Inspection #702501767 on 8/19/23. The following Corrective Actions were issued and original due dates will remain on any that are still unresolved.

1. Debris. (Removed)
 2. Unmarked anchors. (Unresolved)
 3. Insufficient Stormwater BMPs. (Unresolved)
 4. No record of Mechanical Integrity Test. (Unresolved)
- Refer to Inspection Photos for observed compliance issues.

While there during normal operations the following compliance issues were observed:

1. Unused equipment
2. Weeds

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	801-571-5890 / 970-620-2257 / 911	
Corrective Action:		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Oil and Gas Locations will be kept free of all Undesirable Plant Species.		
Corrective Action:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.	Date:	10/10/2023
Type	UNUSED EQUIPMENT		
Comment:	Pumping unit not in service		
Corrective Action:	All equipment not hooked up or out of service will be removed from location.	Date:	11/02/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 0		
Comment:	1 unmarked cable anchor. 1 cable anchor marked with debris.		
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.	Date:	10/17/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 228525 Type: WELL API Number: 103-05400 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Well has not produced since September 2001. Open hole.
Well needs to be Produced or Plugged.
Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well
can only be returned to SI status if it has produced (without mechanic intervention) within
2 years per Rule 319.b.

Corrective Action: Corrective Action issued 8/19/23. Search of ECMC database resulted in no
correspondance within the 30 day time frame.

Date: 09/25/2023

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater BMPs need implementation and maintenance.

Corrective Action: Provide proper Stormwater BMPs to control runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Vehicle tracking BMPs to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Date: 09/10/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501926	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272357