

Final Reclamation and Stormwater Inspection

Date: 09/21/2023

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 318739

Inspection Document #: 708200576

Weld County, CO

NESW Section 7 T2N R66W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Kelly 1A
Location ID: 318739



Photo 1. Taken near the entrance to the location. Photo illustrates that the approach/access road entrance has not been reclaimed and a cattle guard remains.

Inspection Photos
Location Name: Kelly 1A
Location ID: 318739



Photo 2. Taken at the entrance to the location. CO Listed Noxious weeds- common mullein and scotch thistle pictured.

Inspection Photos
Location Name: Kelly 1A
Location ID: 318739



Photo 3. Taken east of the entrance. Photo illustrates that the access road does not appear to be progressing towards reclamation standards and is not reflective of adjacent reference areas.

Inspection Photos
Location Name: Kelly 1A
Location ID: 318739



Photo 4. Taken near the former well location. Reclaimed areas do not appear to be progressing towards Rule 1004 standards and regulations with evidence of bare/exposed soils and CO Listed Noxious weed - field bindweed.

Inspection Photos
Location Name: Kelly 1A
Location ID: 318739



Photo 5. Close up photo taken near the former well location. Field bindweed and debris observed on location.

Inspection Photos
Location Name: Kelly 1A
Location ID: 318739



Photo 6. Taken from the northern/eastern side of the former location. See comments in Photo 4.

Inspection Photos
Location Name: Kelly 1A
Location ID: 318739



Photo 7. Taken south of the reclaimed location. Reference area pictured.