

Final Reclamation and Stormwater Inspection

Date: 09/21/2023

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 318057

Inspection Document #: 708200577

Weld County, CO

SWSW Section 30 T3N R66W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Lorenz Federal #1
Location ID: 318057



Photo 1. Taken west of the former well location. The former wellhead location (red circle) appears to be progressing towards Rule 1004 standards and regulations, though some undesirable vegetation was observed (e.g. kochia). The production facilities pictured in the background need to be decommissioned and reclaimed.

Inspection Photos
Location Name: Lorenz Federal #1
Location ID: 318057



Photo 2. Reclamation rules require all debris, abandoned gathering line risers, flowline risers, and equipment (regardless of ownership) to be removed within three months of plugging (03/23/2018) the associated facility. The Operator will need to decommission the production facilities and perform reclamation.

Inspection Photos
Location Name: Lorenz Federal #1
Location ID: 318057



Photo 3. See comments in Photo 2.

Inspection Photos
Location Name: Lorenz Federal #1
Location ID: 318057



Photo 4. See comments in Photo 2.

Inspection Photos
Location Name: Lorenz Federal #1
Location ID: 318057



Photo 5. See comments in Photo 2.

Inspection Photos
Location Name: Lorenz Federal #1
Location ID: 318057



Photo 6. See comments in Photo 2.

Inspection Photos
Location Name: Lorenz Federal #1
Location ID: 318057



Photo 7. See comments in Photo 2.

Inspection Photos
Location Name: Lorenz Federal #1
Location ID: 318057



Photo 8. Taken from the center portion of the production facilities. Erosion degradation (e.g. rilling) pictured.

Inspection Photos
Location Name: Lorenz Federal #1
Location ID: 318057



Photo 9. Taken from the northern portion of the production facilities. Erosion degradation pictured.

Inspection Photos
Location Name: Lorenz Federal #1
Location ID: 318057



Photo 10. Off location sediment transport is evident as no stormwater control measures were observed during this inspection.