

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2023

Submitted Date:

10/04/2023

Document Number:

712700697

**FIELD INSPECTION FORM**Loc ID 325264 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10734

Name of Operator: HIGH RIVER RESOURCES OPERATING LLC

Address: 3838 OAK LAWN AVE SUITE 710

City: DALLAS State: TX Zip: 75219

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

27 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Mcdonough, Corey		corey.mcdonough@state.co.us	
Vaughn, Robert		rvaughn@highriverllc.co	Primary Contact
Archuleta, Amy		aarchuleta@highriverllc.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214425	WELL	PR	02/01/2019	GW	067-06026	UTE 3	PR

**General Comment:**

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Dirt and gravel, private property.			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	OTHER			
Comment:	Warning signs at location entrance. Warning signs on skid compressor.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Metal sign posted at wellhead.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Contents and volume labels, NFPA placard on produced water tank.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on wellhead sign.			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Observed impacted material on ground surrounding skid mounted compressor. Impacted area approximately 10-ft. x 5-ft. See photos #4 & #5.			
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.			Date: 10/18/2023
Type	WEEDS			
Comment:	Undesirable vegetation growing near separator and wellhead.			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	TANK BATTERY			
Comment:	T-post and hog wire around produced water tank.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Pipe rail fencing around skid mount compressor.			
Corrective Action:				Date:

Type	OTHER				
Comment:	Pipe rail enclosure around above ground valve.				
Corrective Action:				Date:	
<b>Equipment:</b>					corrective date
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Telemetry				
Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:	On separator vent stack.				
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Unitized vertical separator/dehydrator skid mounted.				
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	Accessible				
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	
Type: Gathering Line	# 1				
Comment:	2" line from meter to above ground valve.				
Corrective Action:				Date:	
Type: Compressor	# 1				
Comment:	Skid mounted				
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:	2" line from separator to digital meter.				
Corrective Action:				Date:	
Type: Flow Line	# 3				
Comment:	2-2" lines from wellhead to separator. 1-2" line from separator to compressor.				
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:	Wellhead				
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	Open Top		37.006870,-107.636630

Comment:		Screened, open top steel tank.					
Corrective Action:						Date:	

**Paint**

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			

Comment:		Plastic liner on base.					
Corrective Action:						Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	<50 BBLs	Open Top		37.006950,-107.636650		

Comment:		Partially buried, plastic liner inside, screened, open top steel tank. Tank is labeled Harvest Midstream.					
Corrective Action:						Date:	

**Paint**

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			

Comment:							
Corrective Action:						Date:	

**Venting:**

Yes/No	NO					
Comment:						
Corrective Action:					Date:	

**Flaring:**

Type							
Comment:							
Corrective Action:						Date:	

**Inspected Facilities**Facility ID: 214425 Type: WELL API Number: 067-06026 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/10/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					
Ditches	Pass	Ditches	Pass			
Gravel	Pass					
Berms	Pass	Culverts	Pass	Material Handling And Spill Prevention	Pass	Containers within containment.
Rip Rap	Pass	Gravel	Pass			
Compaction	Pass					

Comment: Numerous wattles missing, numerous old staking protuding. See photo #6.

Corrective Action: Repair stormwater BMPs, remove staking as debris from old BMP installations.

Date: 10/19/2023

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700703	Well Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273570">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6273570</a>