


Inspection Photos
Location Name: Bledsoe 16-34-5-44
API Number: 125-09686



1. Well sign at well location. Wrong name correct API.



2. View of Wellhead. Note vegetation.

Inspection Photos
Location Name: Bledsoe 16-34-5-44
API Number: 125-09686



3. Gas leaking from collar and nipple connection.



4. Pump Jack cement pad and debris. Note vegetation.

Inspection Photos
Location Name: Bledsoe 16-34-5-44
API Number: 125-09686



5. Pump Jack barriers left inside fencing. Note vegetation.



6. Downed Pump Jack Power and Control Panel. Note vegetation.

Inspection Photos
Location Name: Bledsoe 16-34-5-44
API Number: 125-09686



7. Production related debris by Meter Shed.




8. Meter Shed.

Inspection Photos
Location Name: Bledsoe 16-34-5-44
API Number: 125-09686



9. Chart found in Meter Box at time of inspection.



10. Meter Calibration Log found in Meter Shed at time of inspection.

Inspection Photos
Location Name: Bledsoe 16-34-5-44
API Number: 125-09686



11. One located Deadman not marked. Unable to locate remaining three.



12. Location overview. Noted vegetation inside fencing.