

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2023

Submitted Date:

09/28/2023

Document Number:

712700680

FIELD INSPECTION FORMLoc ID 414270 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		Maralextech@gmail.com	All SW Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
O'Hare, Mickey		amohare@maralexinc.com	
, O'hare		mollieo@maralexinc.com	San Juan inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287557	WELL	PR	04/25/2007	CBM	067-09255	GOSNEY 1-A	PR
294961	WELL	PR	08/22/2008	CBM	067-09507	GOSNEY 4-A	PR
414273	WELL	PR	12/01/2010	CBM	067-09798	GOSNEY 2-A	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a follow up field inspection to verify completion of corrective actions identified in FIR Document #712700542 submitted on 8/18/2023.

Equipment inventory listed on previous inspection, no change to equipment on location.

New corrective actions identified, see Signs section.

Location			
Lease Road:			
Type	Access		
comment:	Road through active gravel operations.		
Corrective Action		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Metal signs posted on separators.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank volume capacity not labeled. See Photo #5 & #6. Corrective action identified in FIR Doc.#712700542. Corrective action not completed, date is retained.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	10/18/2023
Type	CONTAINERS		
Comment:	Labels on containers not legible. See Photo #3 & #4.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/28/2023
Emergency Contact Number:			
Comment:	Posted on wellhead sign.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	DEBRIS		
Comment:	Sections of pumpjack fence panels on ground. See Photos #7 & #8. Corrective action identified in FIR Doc.#712700542. Corrective action not completed, date is retained.		
Corrective Action:	Return to service or remove if non-serviceable or no longer needed for ongoing operations.	Date:	09/02/2023
Type	UNUSED EQUIPMENT		
Comment:	Observed disconnected lube oil container and chemical container next to wellhead. See Photo #1 & #2. Corrective action identified in FIR Doc.#712700542. Corrective action not completed, date is retained.		
Corrective Action:	Return to service, or remove if no longer needed for ongoing operations.	Date:	08/25/2023
Type	OTHER		
Comment:	Observed impacted material on ground around prime mover. See Photos #9 & #10. Corrective action identified in FIR Doc.#712700542. Corrective action not completed, date is retained.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes.	Date:	08/23/2023
Type	WEEDS		
Comment:	Weeds growing around pumpjacks, tank containment berms. See Photos #11 & #12. Corrective action identified in FIR Doc.#712700542. Corrective action not completed, date is retained.		
Corrective Action:	Remove weeds per Rule 606.	Date:	09/01/2023
Overall Good: <input type="checkbox"/>			
Spills:			

Inspector Name: Pattillo, Curtis

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities

Facility ID: 287557 Type: WELL API Number: 067-09255 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 09/19/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

Facility ID: 294961 Type: WELL API Number: 067-09507 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 09/19/2023Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 3 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

Facility ID: 414273 Type: WELL API Number: 067-09798 Status: PR Insp. Status: PR

Producing WellComment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 07/28/2022Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 62 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: No Form 17 in well file for 2023.Corrective Action: Perform annual bradenhead test and submit Form 17 per Rule 419.c.Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Ditches	Pass	Material Handling And Spill Prevention	Pass	Containers within containment.

Comment: No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403544585	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6267533
712700681	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6267522