

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/27/2023

Submitted Date:

09/27/2023

Document Number:

713300130

FIELD INSPECTION FORM

Loc ID 331631 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS
Silver, Randy		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264084	WELL	SI	12/01/2021	OW	123-21008	CONNER 41-4	SI

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	good		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:	chain link panels around all production equipment		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	chain link panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	metal panels		
Corrective Action:		Date:	

Equipment:

Type: Emission Control Device	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment: automation and radio		Date:
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER		OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	150 Bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: shared with condensate tank				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE		300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 264084 Type: WELL API Number: 123-21008 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: No current MIT on record or delinquent as required by Rule 417

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210. Date: 10/27/2023

BradenHead

Date of Last Brhd Test: 02/23/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Wednesday 2-27-2023 at approximately 13:00, I, Inspector Michael Kester, conducted an on-site inspection. Location: Conner 41-4 Operator: Crestone Peak Resources API#: 123-21008 County: Weld While there, I observed well that appeared to be shut in During this inspection the following possible compliance issues were observed: MIT required, Rule 417d, corrective action date 10-27-2023 Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>This inspection does not nullify any orders or NOAV from the COGCC This is a continuing education inspection</p>	kesterm	09/27/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403543921	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6266695
713300131	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6266692