

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/05/2023

Document Number:

699107500

## FIELD INSPECTION FORM

 Loc ID 327604 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments2 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
Tibbs, Dan	970-539-0664	Dtibbs@kpk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
327604	LOCATION	AC			-	PARMLEE-63N62W 1SWNW	SI

**General Comment:**[This is an inspection on the tank battery](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	WEEDS		
Comment:	Overgrown vegetation throughout the location need to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	10/17/2023

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas Meter Run has panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	

**Equipment:**

Type	#	Capacity	Type	Tank ID	SE GPS	corrective date
Gas Meter Run	# 1					
Comment:						
Corrective Action:						Date:
Vertical Heated Separator	# 1					
Comment:						
Corrective Action:						Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		40.257100,-104.275200

Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient		Inadequate	
Comment:	Berms around the tank are weathered and need repaired. See attached photos.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.				Date: 10/20/2023
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.256700,-104.275600
Comment:					
Corrective Action:					
Date:					
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Date:					
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					
Date:					
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					
Date:					

**Inspected Facilities**

Facility ID: 327604 Type: LOCATION API Number: - Status: AC Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>ECMC Inspection Report Summary</b>                      On Tuesday 10/3/23 at approximately 0931hrs I, Inspector Adam Burns, Conducted an on-site inspection at PARMLEE-63N62W 1SWNW Tank Battery of KP Kauffman Company INC.                      Location Id: 327604 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Overgrown vegetation throughout the location need to be removed for good housekeeping. Comply with Rule 606. With a Corrective Action date of 10/20/23                      Berms around the tank are weathered and need repaired. Repair or install berms or other secondary containment devices per Rule 603.o. With a Corrective Action date of 10/20/23                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the inspection report.</p>	burnsa	10/05/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699107501	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275472">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6275472</a>