

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/05/2023

Submitted Date:

10/06/2023

Document Number:

712700712

FIELD INSPECTION FORM

Loc ID 325207 Inspector Name: Pattillo, Curtis On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10684
Name of Operator: EPIC ENERGY LLC
Address: 332 RD 3100
City: AZTEC State: NM Zip: 87410

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 19 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Thompson, Paul		paul@walsheng.net	Principal Agent
Labowskie, Steve		steve.labowskie@state.co.us	
Smith, Arleen		arleen@walsheng.net	SW Inspections
Martinez, Shawna		shawna@walsheng.net	SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214284	WELL	PR	08/01/2021	GW	067-05619	MCCULLOCH 3	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location			
Lease Road:			
Type	Access		
comment:	Long access road from County Road 213. Dirt surfaced lease road bisects the location.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank has non-legible contents and volume labels, no NFPA placard.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Metal sign posted on meterhouse.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 hour operator contact number is functional, well location signage missing local emergency services number.		
Corrective Action:	Post local emergency services number or 911 on well location signage.		Date: 11/06/2023
Good Housekeeping:			
Type	OTHER		
Comment:	A well-tie pipeline ROW and access road bisects the location.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Pipe rail and hog wire around produced water tank.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Pipe rail around above ground valve.		
Corrective Action:			Date:
Equipment:			
Type: Deadman # & Marked	# 2		corrective date
Comment:			
Corrective Action:			Date:
Type: Gathering Line	# 1		
Comment:	Above grond valve set.		

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	2" line from separator to meterhouse. Calibration date 10/2/2023.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Cathodic protection		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Accessible		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:	2-2" lines from wellhead to separator. 1-1" line from wellhead to separator.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		37.152630,-107.926410
Comment:	Approximately 1 1/2" diameter hole in tank lid.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 214284 Type: WELL API Number: 067-05619 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/15/2022 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
		Gravel	Pass			
Berms	Pass	Culverts	Pass			

Comment: Location is mostly vegetated with grasses, forbs, shrubs, and trees.
No visible erosion or sediment migration observed during inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700718	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6276379