

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2023

Submitted Date:

10/06/2023

Document Number:

707601915

**FIELD INSPECTION FORM**Loc ID 323559 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
323559	LOCATION	AC			-	WPF III-66N64W 18NWNE	IO

**General Comment:**

This is a BATTERY inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 1 Location ID  
(323559).

(Well(s): 1: Temporarily Abandoned | TA).

Centralized Battery formerly served 2 Location IDs  
(310589, 420580).

(Well(s): 2: Plugged &amp; Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID  
(Pending).

Reference:

A.) Field Inspection Report doc. #707601913 and/or Location ID #323559  
for TA Well(s) info.B.) Field Inspection Report doc. #707601915 and/or Location ID #323559  
for Battery / Facility, Equipment info.

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	Gas Sales: Calibration card(s) indicates calibration > 1 year. Last calibration: 03/19/2019. Inactive, NO production.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		

Comment: 1: Crude storage vapor line combustor(s). Controls crude oil tank(s) vapors. Pilots: OFF   Shut-down. 1: Separator vapor line combustor(s). Controls separator(s) vapors. Pilots: OFF   Shut-down.			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment: Battery site: 1: Solar power bank. 2: ECD scrubber(s).			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment: Centralized Battery serves 1 Location ID (323559). (Well(s): 1: Temporarily Abandoned   TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	3	300 BBLs	STEEL AST		40.492857,-104.592665	
Comment: <a href="#">Equalizer line(s) connect crude oil tanks.</a>						
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: <a href="#">Berms shared w/ crude oil tank(s), produced H2O vault(s).</a>						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Summary:</b></p> <p>On FRI 10/06/2023 at approximately 15:38 hrs. I, Bret Evins, conducted an onsite inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: WPF III-66N64W/18NWNE  Location ID: 323559  Well Name(s):  WPF III A18-2.  API:  123-13195.  Location County: Weld County, Colorado  Weather: Mostly Sunny, dry.</p> <p>While there, I observed:  Well(s): 1: Temporarily Abandoned   TA.  Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 1 Location ID (323559).  (Well(s): 1: Temporarily Abandoned   TA).</p> <p>Centralized Battery formerly served 2 Location IDs (310589, 420580).  (Well(s): 2: Plugged &amp; Abandoned   PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference:  A.) Field Inspection Report doc. #707601913 and/or Location ID #323559 for TA Well(s) info.  B.) Field Inspection Report doc. #707601915 and/or Location ID #323559 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/06/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601916	Site photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6276944">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6276944</a>