

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/13-33

Location ID: 323902

Date: 10/4/2023



Entrance to Location – Photo #06725



NE Corner of Location – Photo #06726



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/13-33

Location ID: 323902

Date: 10/4/2023



NW Corner of Location – Photo #06727



Wellheads – Photo #06728

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/13-33

Location ID: 323902

Date: 10/4/2023



Separators – Photo #06730



Tank Battery – Photo #06729



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/13-33

Location ID: 323902

Date: 10/4/2023



Unsecured Separator Hatch – Photo #06731



Unsecured Separator Hatch – Photo #06732

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/13-33

Location ID: 323902

Date: 10/4/2023



Rill Erosion Cutting Through Lease Road – Photo #06734



Rill Erosion Cutting Through Lease Road – Photo #06735