

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NWSE

Location ID: 335214

Date: 10/4/2023



Entrance to Location – Photo #06745



NW Corner of Location – Photo #06748



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NWSE

Location ID: 335214

Date: 10/4/2023



Wellheads – Photo #06746



Separators – Photo #06749



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NWSE

Location ID: 335214

Date: 10/4/2023



Tank Battery – Photo #06750



Location Lacks Stabilization – Photo #06747



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NWSE

Location ID: 335214

Date: 10/4/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #06752**



**Rill Erosion Cutting Through Lease Road – Photo #06753**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NWSE

Location ID: 335214

Date: 10/4/2023



**Rill Erosion Cutting Through Lease Road – Photo #06754**