

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION-66S96W/33NWSE

Location ID: 335237

Date: 10/4/2023



Entrance to Location – Photo #06756



Wellheads – Photo #06757

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION-66S96W/33NWSE

Location ID: 335237

Date: 10/4/2023



Separators – Photo #06758



Tank Battery – Photo #06760

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION-66S96W/33NWSE

Location ID: 335237

Date: 10/4/2023



Oct 4, 2023 at 10:17:42
3555 CR-215
Parachute CO 81635
United States



Oct 4, 2023 at 10:18:18
3555 CR-215
Parachute CO 81635
United States

Unsecured Hatch on Separator – Photo #06759

Location Lacks Stabilization – Photo #06762

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION-66S96W/33NWSE

Location ID: 335237

Date: 10/4/2023



Oct 4, 2023 at 10:19:29
3555 CR-215
Parachute CO 81636
United States

Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06763