

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESE

Location ID: 335353

Date: 10/4/2023



Entrance to Location – Photo #06765



SW Corner of Location – Photo #06766



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESE

Location ID: 335353

Date: 10/4/2023



Wellheads – Photo #06767



Separators – Photo #06768



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESE

Location ID: 335353

Date: 10/4/2023



Tank Battery – Photo #06771



Unsecured Hatch on Separators – Photo #06769



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESE

Location ID: 335353

Date: 10/4/2023



Location Lacks Stabilization – Photo #06772



Location Lacks Stabilization – Photo #06773



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33NESE

Location ID: 335353

Date: 10/4/2023



**Rill Erosion Cutting Through Access Road – Photo #06774**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #06775**