

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/06/2023

Document Number:

707800653

FIELD INSPECTION FORM

 Loc ID 335651 Inspector Name: Ramsey, Scott On-Site Inspection
 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202
Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282285	WELL	PR	12/01/2018	GW	045-11725	N PARACHUTE WF09C-25I25A596	PR
292025	WELL	PR	12/01/2018	GW	045-14573	N PARACHUTE WF10B-25I25A596	PR
292026	WELL	PR	12/01/2018	GW	045-14572	N PARACHUTE WF10C-25I25A596	PR
292027	WELL	PR	12/01/2018	GW	045-14571	N PARACHUTE WF09A-25I25A596	PR
292028	WELL	PR	12/01/2018	GW	045-14570	N PARACHUTE WF16A-25I25A596	PR
292029	WELL	PR	12/01/2018	GW	045-14569	N PARACHUTE WF09D-25I25A596	PR
292030	WELL	PR	12/01/2018	GW	045-14568	N PARACHUTE WF09B-25I25A596	PR
292031	WELL	PR	12/01/2018	GW	045-14567	N PARACHUTE WF10A-25I25A596	PR
292032	WELL	PR	12/01/2018	GW	045-14566	N PARACHUTE WF10D-25I25A596	PR

General Comment:

ECMC Inspection Report Summary
 On Thursday 10/5/2023, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus I25A, at Location # 335651 in Garfield county Colorado.
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
 While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.
 This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Ancillary equipment	# 2		corrective date
Comment:	Chemical tanks in plastic containments		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 9		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 18		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		
Comment:	1 tank is heated				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	282285	Type:	WELL	API Number:	045-11725	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	292025	Type:	WELL	API Number:	045-14573	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	292026	Type:	WELL	API Number:	045-14572	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	292027	Type:	WELL	API Number:	045-14571	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	292028	Type:	WELL	API Number:	045-14570	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	292029	Type:	WELL	API Number:	045-14569	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	292030	Type:	WELL	API Number:	045-14568	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	292031	Type:	WELL	API Number:	045-14567	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

Facility ID: 292032 Type: WELL API Number: 045-14566 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800658	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6277086