

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUNN B9E Pad

Location ID: 334833



Photo # 1882 From entrance to location




Photo # 1883 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC DUNN B9E Pad
Location ID: 334833



Photo # 1884 Location



Photo # 1885 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUNN B9E Pad

Location ID: 334833



Photo # 1886 Location



Photo # 1887 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC DUNN B9E Pad
Location ID: 334833



Photo # 1888 Location



Photo # 1889 Flowline heating insulation open ended

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUNN B9E Pad

Location ID: 334833




Photo # 1890 Debris