

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUMAS P14 Pad

Location ID: 334619



Photo # 1648 From entrance to location



Photo # 1649 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUMAS P14 Pad

Location ID: 334619



Photo # 1650 Location



Photo # 1651 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC DUMAS P14 Pad
Location ID: 334619



Photo # 1652 Location



Photo # 1653 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUMAS P14 Pad

Location ID: 334619



Photo # 1654 Location



Photo # 1655 Rupture disc vent line lacks cap

Inspection Photos

Location Name: CAERUS PICEANCE LLC DUMAS P14 Pad

Location ID: 334619



Photo # 1656 Rupture disc vent line lacks cap