

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2023

Submitted Date:

10/02/2023

Document Number:

688500344

FIELD INSPECTION FORMLoc ID 464916 Inspector Name: CANFIELD, CHRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 4680

Name of Operator: DCP OPERATING COMPANY LP

Address: 2331 CITYWEST BLVD., S812-02

City: HOUSTON State: TX Zip: 77042

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chandler Cole		chandler.e.cole@p66.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452046	SPILL OR RELEASE	CL	01/30/2018		-	Doris 1/ Dottie 12-34 Tank Leak	CL
484701	SPILL OR RELEASE	CL	09/01/2023		-	CR55/CR4 (AT-1-1-1-6-3) 5/2023	CL

General Comment:

Environmental inspection of Spill/Release ID 484701.

Note: the subject location was inspected on 08/24/23, however an IT issue resulted in a delay in posting the inspection. Photos taken during the inspection depict conditions on 08/24/23.

Inspected Facilities									
Facility ID:	<u>452046</u>	Type:	<u>SPILL OR</u>	API Number:	<u> - </u>	Status:	<u>CL</u>	Insp. Status:	<u>CL</u>
Facility ID:	<u>484701</u>	Type:	<u>SPILL OR</u>	API Number:	<u> - </u>	Status:	<u>CL</u>	Insp. Status:	<u>CL</u>

Environmental**Spills/Releases:**

Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: [See documents indexed to Spill/Release ID 48470.](#)[See documents indexed to Remediation Project 31076.](#)Corrective Action: [Provide information outlined below to the ECMC Engineering Integrity Unit \(compliance of COGCC series 1100 flowline rules\):1. Description of flowlines exposed in excavation \(dump, process, etc\)2. Status of lines exposed in excavation \(active, out of service, etc\)3. A copy of the latest flowline pressure testing data and chart \(1104.h\)4. Schedule of repairs to be completed \(1102.j\) 5. Post-repair integrity confirmation data \(1102.j.4\)](#)

Date: 11/01/2023

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Lat _____

Long _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment

User

Date

[Environmental inspection of Spill/Release ID 484701.](#)

canfielc

10/02/2023

[Note: the subject location was inspected on 08/24/23, however an IT issue resulted in a delay in posting the inspection. Photos taken during the inspection depict conditions on 08/24/23.](#)[Follow-up inspection required due to lag time in posting this inspection.](#)**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403547046	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6270551
688500345	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6270543