

# Inspection Photos

Loc: 324843

Operator: CHEMCO INC

Inspection Date: 10/5/2023

County: Kiowa



## Inspection Photos



**Photo 1.** Facing toward the well site. Operators well sign is laying on the ground at red arrow.



## Inspection Photos



**Photo 2.** There is still unused parts that remain around the pumpjack.



## Inspection Photos



**Photo 3.** Facing toward the wellhead. There is oil stained soils. It appears dirt was placed over this area to cover up the impacted soils. Impacted soil need to be immediately excavated, cleaned up, and properly disposed per Rule 912.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:324843 | Date: 10/5/2023

## Inspection Photos



**Photo 4.** There is impacted soils that were observed in an area approximately 20x40 feet in size. After further investigation the spill appears to be reportable under 912.b. Red arrows point to areas of oil stained soils.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:324843 | Date: 10/5/2023

## Inspection Photos



**Photo 5.** Facing northeast toward the separator. A berm was placed around the separator however the earthen berm is not properly built.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:324843 | Date: 10/5/2023

## Inspection Photos



**Photo 6.** The berm around the separator is not compacted and built sufficiently for containment.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:324843 | Date: 10/5/2023

## Inspection Photos



**Photo 7.** There is oil saturated soils that still remain at the separator. There was dirt spread over the stained soil to cover this spill. Impacted soil need to be immediately excavated, cleaned up, and properly disposed per Rule 912.



## Inspection Photos



**Photo 8.** Facing toward the tank battery.



## Inspection Photos



**Photo 9.** There is oil stained soils near the tank at the red arrow. There is an unused pipe riser at the yellow arrow and various plastic debris.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:324843 | Date: 10/5/2023

## Inspection Photos



**Photo 10.** There is saturated oily soils at the tank battery that have not been cleaned up. Previous corrective action was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:324843 | Date: 10/5/2023