

Inspection Photos

Loc: 324848

Operator: CHEMCO INC

Inspection Date: 10/5/2023

County: Kiowa



Inspection Photos



Photo 1. Facing northeast toward the tank battery. Berm is not adequate for containment.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324848 | Date: 10/5/2023

Inspection Photos



Photo 2. The pipe has been reinstalled at the tank however oily stained soil still remain.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324848 | Date: 10/5/2023

Inspection Photos



Photo 3. The berm around the tank is insufficiently sized to contain a spill./ There is oily contaminated soils on the berm (red arrow) that needs to be cleaned up and removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324848 | Date: 10/5/2023

Inspection Photos



Photo 4. Facing northeast at the tank battery. This unused area of the location needs to be reclaimed.



Inspection Photos



Photo 5. Facing along the access road at the cattleguard. The cattleguard has been cleaned out.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324848 | Date: 10/5/2023

Inspection Photos



Photo 6. Facing toward the wellsite.



Inspection Photos



Photo 7. There is an open pipe riser that needs OOSLAT or needs to be removed.



Inspection Photos



Photo 8. The fence around the pumpjack is not adequate to prevent livestock entry and is only 2ft. Tall near the well sign. There are wires stick out (red arrow) which could injury livestock..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324848 | Date: 10/5/2023