

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/05/2023

Submitted Date:

10/09/2023

Document Number:

710500050

FIELD INSPECTION FORMLoc ID 384662 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16520

Name of Operator: CHEMCO INC

Address: 6970 SOUTH HOLLY CIR STE 206

City: CENTENNIAL State: CO Zip: 80112

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------------------|---------------------------|---------|
| Costa, Ryan | | ryan.costa@state.co.us | |
| Welsh, Brian | | brian.welsh@state.co.us | |
| Neher, Gray | 303-771-7777/9006 | bogray@msn.com | |
| Sanchez, Chris | | chris.sanchez@state.co.us | |
| Neher, Morgan | | morgan@chemco-og.com | |

General Comment:

This is an Environmental Inspection for the Donohoe 4-A, Location ID 384662 active well location and Tank Battery, located in Kiowa County, Co

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: Yes

Comment:

Oil Stains observed within Secondary Containment for Tank Battery, Maintain Equipment per Rule 608.e and cleanup impacted soils

☐ Multiple Spills and Releases?**Fencing/:**

Type PUMP JACK

Comment:

Fencing around Pumping Unit needs Inadequate

Corrective Action:

Repair and maintain fencing per Rule 608.e

Date: 11/08/2023

Equipment:

corrective date

Type: Pump Jack

1

Comment:

Oil Stains Observed at well head

Corrective Action:

Cleanup affected soil and maintain equipment within compliance of rule 608.e

Date: 11/08/2023

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|-----------|---|----------|-----------|---------|--------|
| CRUDE OIL | 2 | | STEEL AST | | , |

Comment:

Tank Placards illegible

Corrective Action:

Comply with Rule 605.h. for Tank and Container labels.

Date: 12/13/2023

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|------------|---------------------|---------------------|-------------|
| Earth | Inadequate | Walls Insufficient | | Inadequate |

Comment:

Tank Battery Berms appear to be inadequate, Operator shall calculate volume to assure compliance with Rule 603.o.

Corrective Action:

Comply with, Rule 603.o.

Date: 11/21/2023

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

COGCC Comments

| Comment | User | Date |
|---|-----------|------------|
| Install/repair fencing around pumping unit. | sanchezcc | 10/09/2023 |
| Inspect and measure Tank Battery Secondary containment to assure compliance with Rule 603. o. | sanchezcc | 10/09/2023 |
| Replace Placard labels for Tank Battery, Cleanup stained soil within Secondary Containment. | sanchezcc | 10/09/2023 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------|---|
| 710500051 | Location Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6278429 |