



**Location**

Overall Good:

Emergency Contact Number: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Mechanical issue on wellhead, gas was observed leaking from wellhead, see pictures and video.		
Corrective Action:	Comply with rule 606	Date:	10/04/2023
Type	OTHER		
Comment:	At time of inspection hydrocarbon odors were present on location. See pictures and video.		
Corrective Action:	Odor detected by COGCC staff related to referenced oil and gas location, actions must be taken to stop the odor per Rule 426. Additionally, this matter has been referred to the CDPHE for possible further investigation.	Date:	10/04/2023

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 242038 Type: WELL API Number: 123-09829 Status: PR Insp. Status: PR

**Producing Well**

Comment:	<u>PR</u>	
Corrective Action:		Date:

**BradenHead**

Date of Last Brhd Test: 03/15/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On 10/3/23 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- jacobucci 4                      Company Name- KPK                      API- 05-123-09829                      In Adams County Colorado.                      While there, I observed SI well                      During this inspection the following possible compliance issues were observed:                      Odors. Rule 426. 10/4/23                      Mechanical issue. Rule 606. 10/4/23                      At time of inspection gas was observed leaking from wellhead, and hydrocarbon odors were present. Left message with KPK emergency number, and also called Mani Silva with KPK to inform them of the issue.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This inspection does not nullify any orders or corrective actions from the ECMC.                      At time of inspection weather conditions were warm, partly cloudy, light wind.                      This is a summary of inspection report.</p>	medinaj	10/03/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403549129	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272602">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272602</a>
699505044	inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272588">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272588</a>
699505045	Inspection video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272589">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6272589</a>