

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/09/2023

Submitted Date:

10/09/2023

Document Number:

712700719

FIELD INSPECTION FORMLoc ID 320886 Inspector Name: Pattillo, Curtis On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69805

Name of Operator: PETROX RESOURCES INC

Address: 12600 W COLFAX AVENUE #C-440

City: LAKEWOOD State: CO Zip: 80215

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Nystrom, Dusty		nystrow@yahoo.com	All SW Inspections
Clark, Ryan		ryan@petrox-resources.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277656	WELL	PR	03/01/2021	CBM	007-06213	FOSSET GULCH UNIT 9U 2	PR

General Comment:

SW Compliance Specialist Curtis Pattillo conducted a field inspection of the access road and well location.

Location					
Lease Road:					
Type	Access				
comment:	Accessed from Fossett Gulch road.				
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:	Metal sign posted at location entrance.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	24 hour operator contact number is functional, well location signage missing local emergency services number.				
Corrective Action:	Post local emergency services number or 911 on well location signage.				Date: 11/10/2023
Good Housekeeping:					
Type	WEEDS				
Comment:	Musk thistle was recorded on previous inspection FIR Doc.#693903650 submitted 9/14/2021. Less than 5 individual musk thistle plants observed. Approximately 6 individual Canada thistle plants were observed around the location.				
Corrective Action:					Date:
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	OTHER				
Comment:	Pipe rail fencing at buried valve can.				
Corrective Action:					Date:
Type	WELLHEAD				
Comment:	Pipe rail fencing around pumpjack and prime mover.				
Corrective Action:					Date:
Equipment:					
					corrective date
Type: Ancillary equipment	# 1				
Comment:	Wellhead				
Corrective Action:					Date:
Type: Deadman # & Marked	# 3				
Comment:					
Corrective Action:					Date:

Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gathering Line	# 1		
Comment:	Buried valve can.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Accessible		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas motor.		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	2" line from separator to digital meter. Meter and separator are unitized, skid mounted. Calibration date 8/10/2023.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	On separator vent stack.		
Corrective Action:			Date:
Type: Flow Line	# 3		
Comment:	1-2" line from wellhead to separator. 1-2" line from separator to wellhead. 1-2" line from separator to prime mover.		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	277656	Type:	WELL	API Number:	007-06213	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	08/18/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:	NONE				
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					
Berms	Pass	Culverts	Pass			
Ditches	Pass	Ditches	Pass			
Waddles	Pass	Gravel	Pass			

Comment: No visible erosion or sediment migration observed during inspection.Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
712700724	Well Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6278793