

Inspection Photos

Loc: 324795

Operator: WESTERN OPERATING COMPANY

Inspection Date: 10/5/2023

County: Kiowa



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing northwest from the Foster #1 wellsite. There are multiple impacted areas from previous spill. Site investigation and remediation will need to occur.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324795 | Date: 10/5/2023

Inspection Photos



Photo 2. Drone aerial photo facing northwest from the Foster #1 wellsite. There is multiple impacted areas from previous spill. Site investigation and remediation will need to occur.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324795 | Date: 10/5/2023

Inspection Photos



Photo 3. Facing toward the tank battery site. The tanks have been removed however, unused pipe risers and various equipment still remains.



Inspection Photos



Photo 4. Facing northeast toward the wellsite. There is erosion occurring in this area shown at red arrow.



Inspection Photos



Photo 5. Facing northwest where tanks were located. There is oil impacted soils shown at red arrows.



Inspection Photos



Photo 6. Facing toward the northwest side of the location. There is Stormwater erosion occurring off this area of the location. It appears impacted soils have been piled up and are not properly contained.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324795 | Date: 10/5/2023

Inspection Photos



Photo 6. Facing toward the southeast. There is Stormwater erosion occurring off this area of the location. It appears impacted soils have been pled up and are not properly contained.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324795 | Date: 10/5/2023