

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION ENERGY MINING DIV.-66S96W/33SWSE

Location ID: 334868

Date: 10/5/2023



Wellheads – Photo #06814



Separators – Photo #06816

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION ENERGY MINING DIV.-66S96W/33SWSE

Location ID: 334868

Date: 10/5/2023



Tank Battery – Photo #06815



Location Lacks Stabilization – Photo #06817

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNION ENERGY MINING DIV.-66S96W/33SWSE

Location ID: 334868

Date: 10/5/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06818**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06819**