

Inspection Photos

Loc: 324836

Operator: CHEMCO INC

Inspection Date: 10/5/2023

County: Kiowa



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. Vehicle s have driven outside of the access road causing rutting and disturbance. This area needs to be repaired and the access road needs to be stabilized.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:324836 | Date: 10/5/2023

Inspection Photos



Photo 2. Facing east toward the wellsite.



Inspection Photos



Photo 3. There is a barrel that is not in secondary containment and the fence is open on this side which is not preventing livestock entry.



Inspection Photos



Photo 4. There is still oily soils at the base of the pumpjack. It appears some dirt was spread over the stained soils to cover it up in attempt to hide the spill. Previous corrective action was not completed.



Inspection Photos



Photo 5. There is oil stained soils that leaked out of the wellhead all the way to where the red arrow is shown approx. 25'.



Inspection Photos



Photo 6. Facing toward the tank battery. Labeling on the tanks are faded.



Inspection Photos



Photo 7. There is oily soils around the separator that must be cleaned up..

