

Inspection Photos

Loc:324810

Operator: ENERVEST OPERATING LLC

Inspection Date: 10/5/2023

County: Kiowa



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the reclaimed access road. There is vegetation establishing along with undesirable weeds that will need to be controlled.



Inspection Photos



Photo 2. Facing west toward the location. Remediation Project #19874 is ongoing. Reclamation does not appear to be progressing.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:324810 | Date: 10/5/2023

Inspection Photos



Photo 3. There is erosion occurring and stormwater controls are not maintained. Stormwater has eroded underneath the wattles.



Inspection Photos



Photo 4. Facing east were excavated area was backfilled. Perennial vegetation does not appear to be establishing. A soil analysis needs to be performed



Inspection Photos



Photo 5. Facing northeast. There is erosion occurring at the location and soils are not stabilized.



Inspection Photos



Photo 6. Facing west at the location. There is more vegetation establishment at the west side of the location however most is undesirable weeds.



Inspection Photos



Photo 7. Facing southwest. There is erosion occurring at the location and soils are not stabilized.



Inspection Photos




Photo 8. North side of the location outside of the fenced area is a pipe riser that needs to be removed.



Inspection Photos



Photo 9. Facing east at the location. There is more vegetation establishment at the west side of the location however most is undesirable weeds.

