


Inspection Photos
Location Name: Lesser PM J33 7
Location ID: 246209



Wellhead



Berm Permeability no adequate ECMC rules

Inspection Photos
Location Name: Lesser PM J33 7
Location ID: 246209



Tank battery

Inspection Photos
Location Name: Lesser PM J33 7
Location ID: 246209



Meter run not calibrated since 2018

Inspection Photos
Location Name: Lesser PM J33 7
Location ID: 246209



Unused equipment