


Caerus Piceance LLC
Piceance Creek Unit-62S97W 2NWNW
Location ID: 335894



Entrance sign



Access road to facility



Caerus Piceance LLC
Piceance Creek Unit-62S97W 2NWNW
Location ID: 335894



Debris



Rain caps missing from pop off risers

Caerus Piceance LLC
Piceance Creek Unit-62S97W 2NWNW
Location ID: 335894



Debris



Equipment not in service

Caerus Piceance LLC
Piceance Creek Unit-62S97W 2NWNW
Location ID: 335894



Production facility from Southeast corner



Production facility from Northeast corner

Caerus Piceance LLC
Piceance Creek Unit-62S97W 2NWNW
Location ID: 335894



Production facility from Northwest corner



Production facility from Southwest corner

Caerus Piceance LLC
Piceance Creek Unit-62S97W 2NWNW
Location ID: 335894



Access road to well pad from Production facility



Well pad access road from Production facility

Caerus Piceance LLC
Piceance Creek Unit-62S97W 2NWNW
Location ID: 335894



Wellhead signs missing required information



Unmarked anchor

Caerus Piceance LLC
Piceance Creek Unit-62S97W 2NWNW
Location ID: 335894



Unmarked anchor



Debris

Caerus Piceance LLC
Piceance Creek Unit-62S97W 2NWNW
Location ID: 335894



Well pad from Northeast corner



Well pad from Northwest corner

Caerus Piceance LLC
Piceance Creek Unit-62S97W 2NWNW
Location ID: 335894



Well pad from Southwest corner



Well pad from Southeast corner