

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCARBER (RN2) Pad

Location #: 334668



Oct 10, 2023 at 9:47:50 AM



Oct 10, 2023 at 9:47:54 AM

Photo # 2144 From entrance to location

Photo # 2145 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC SCARBER (RN2) Pad
Location #: 334668



Photo # 2146 Location

Photo # 2147 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCARBER (RN2) Pad

Location #: 334668



Photo # 2148 Location



Photo # 2149 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC SCARBER (RN2) Pad
Location #: 334668



Photo # 2150 Location



Photo # 2151 Unmarked deadman

Inspection Photos
Location Name: CAERUS PICEANCE LLC SCARBER (RN2) Pad
Location #: 334668



Photo # 2152 Flowline heating insulation open ended