

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad

Location #: 334638



Photo # 1988 From entrance to location



Photo # 1989 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad

Location #: 334638



Photo # 1990 Location



Photo # 1991 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Photo # 1992 Location



Photo # 1993 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad

Location #: 334638



Photo # 1994 Location



Photo # 1995 Flowline heating insulation open ended



Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad

Location #: 334638



Photo # 1996 Hole in liner/liner needs maintenance



Photo # 1997 Hole in liner/liner needs maintenance

Inspection Photos
Location Name: CAERUS PICEANCE LLC SAVAGE RK1 Pad
Location #: 334638



Photo # 1998 Hole in liner/liner needs maintenance



Photo # 1999 Hole in liner/liner needs maintenance